## MADISON COUNTY BARN DOCUMENTATION PROJECT

Common Identity of Barn: Dolph Robinson barn Address of Barn: 2614 Hamburg Rd., Mars Hill, NC 28754 GPS Location: N35-49.597 / W82-25.989 Elevation: 2696' Township: Beech Glen Vicinity: Upper Paint Fork/Hamburg Approx date/decade built: late 19 <sup>th</sup> early 20 <sup>th</sup> century	Current Owner: Young McQueen Construction Co. Historic Owner(s): Dolph Robinson, Hughie Ray Current Use: abandoned Historic Use: livestock, burley tobacco, storage
	Permission to visit property by: Young McQueer Construction Co., 828-682-7714
ORIGINAL BARN characteristics	
Integrity  High Medium _x_ Low ConditionGoodFair _x_DeterioratedRuin Add. Info.:	
Function of original barn  _x_ general purpose  _x_ livestock/hay  flue-cured tobacco  burley tobacco  bull face tobacco  dairy  other  Add. Info.: this is a 30' X 36' livestock century, with three additions added to the ends	barn in the typical tradition of the late 19 <sup>th</sup> for burley tobacco.
Type Construction of original barn _x_ Post and Beam timber frame mortise and tenon _x_ sawn lumber _x_ hewn timbers _x_ notched logs stud frame	

Add. Info.: log notching is variable, with some V-notches and some rough saddle notches, the craftsmanship being poor throughout. There are large hewn beams throughout. Each element, including the lattice work, framing, board and batten siding, and log building appears to have been done by someone of less skill and commitment to the standard of quality of this period and type of barn. This conclusion requires further evidence however, as there are too few samples to know with certainty. It has also been poorly maintained.

# Add. Info.: assume split oak shingles Roof framing of original barn \_\_ round pole rafters \_\_ milled rafters \_\_ gambrel shallow trusses \_\_ gambrel with post and beam support \_\_ round purlins \_x\_ unknown Add. Info.: the original rafters could have been round pole rafters. Foundation of original barn \_\_ Dry laid stone \_x\_ wood sills on rock piers \_\_ mortared stone \_\_ concrete \_\_ concrete block \_\_ columns/wood piers

## Flooring of original barn

Add. Info.:

- \_x\_ dirt floor
- \_x\_ wood flooring in loft

\_\_ posts on concrete footings

\_\_ concrete slab

Add. Info.:

### Species of wood used in original barn

- \_x\_ chestnut
- \_x\_ other, list known species

Add. Info.:

## Hinges

- \_\_ leather
- \_\_ wooden
- \_\_ wrought iron
- \_x\_ commercial metal
- \_\_ rubber
- \_\_ other

Add. Info.:

#### Fasteners

- \_x\_ wire nails
- \_\_ cut nails
- \_\_ wrought spikes
- \_\_ wood pegs

other Add. Info.:
Add. IIIIO.:
Tobacco tier poles vertical spacing
+/- 2 feet
+/- 3 feet
+/- 4 feet
other, list Add. Info.:
Add. IIIIO
Additional traditional features, list:
ALTERATIONS AND ADDITIONS characteristics
Has the original barn been altered or added to? yes
Description of alterations and additions: Two large additions have been built for burley tobacco, and each mirrors the shape and size of the original barn. Their construction is also of poor quality. Two simple shed roof additions have also been added and are in disrepair. The original barn was altered with vertical and horizontal tier poles to adapt it for hanging burley tobacco. Replacement of wood shingle roof may have included replacement of the original round framing members with sawn lumber, but this is not confirmed.
Condition of alterations good fair
_x_ deteriorated
ruin
Add. Info.:
Function of barn alterations and additions
_x_ general purpose
livestock/hay
flue-cured tobacco
_x_ burley tobacco
bull face tobacco
dairy
_x_ other Add. Info.: one shed addition has sash windows and appears to have been for case house
or other enclosed function.
Type Construction alterations and additions
_x_ Post and Beam
timber frame
mortise and tenon

_x_ sawn lumber
_x_ hewn timbers
notched logs
_x_ stud frame
Add. Info.: hewn timbers were used for some of the sill plates.
Siding materials of alterations and additions
_x_ milled boards
_x_ lattice
exposed logs
board and batten
metal
shingles
_x_ other
Add. Info.: some use of asphalt / tar paper used on siding.
Orientation of siding
angled on diagonal
_x_ vertical
_x_ horizontal
Add. Info.:
Roof pitch or slope of alterations and additions: gable end additions match original slope a 11/12. Shed additions are approx. 3/12 and 1/12.
Roof type of barn alterations and additions
_x_ gable
broken gable
gambrel
_x_ shed
monitor
cupola
other
Add. Info.:
Roofing materials of alterations and additions
split wood shingles
3-V metal
3-u metal
_x_ 5-V metal
stamped metal shingle
tar paper
unknown
other
Add. Info.:

Roof framing of alterations and additions
round pole rafters
_x_ milled rafters
gambrel shallow trusses
gambrel with post and beam support
round purlins
Add. Info.:
Foundation of alteretions and additions
Foundation of alterations and additions
Dry laid stone
_x_ wood sills on rock piers
mortared stone
concrete
concrete block
columns/wood piers
posts on concrete footings
Add. Info.:
Flooring of alterations and additions
_x_ dirt floor
_x_ wood flooring
concrete slab
Add. Info.: wood flooring in the enclosed shed addition
5
Species of wood used in alterations and additions
_x_ chestnut
_x_ other, list known species
Add. Info.: misc species
Hinges/ alterations and additions
leather
wooden
wooden wrought iron
_x_ commercial metal
rubber
other
Add. Info.:
ridi. IIIo
Fasteners/ alterations and additions
_x_ wire nails
cut nails
wrought spikes
wood pegs
other
Add. Info.:

Tobacco tier poles vertical spacing/ alterations and addition	S
+/- 2 feet	
+/- 3 feet	
_x_ +/- 4 feet	
other, list	
Add. Info.:	

Outbuildings: none surviving

Setting and/or Surrounding Land Use: This site is a relatively high elevation farmstead in a relatively narrow valley with little tillable land compared to farms with this type barn owned by a more affluent family. The old house that once stood nearby was a large 2-story frame house that burned in the 1990's.

Historic Information: Surviving family members recall very little about this barn.

Date Photos Taken: Feb 9, 2013

Submitted By

Name: Taylor Barnhill

Address: 226 Beech Glen Rd., Mars Hill, NC 28754 Phone home: Cell: 828-380-9336

Email: taylor.barnhill@yahoo.com