MADISON COUNTY BARN DOCUMENTATION PROJECT

Common Identity of Barn: John Shelton (1882 to	Current Owner: Ben and Roos Geradts
1981) barn	Historic Owner(s): Major Marler, John Shelton
Address of Barn: jnctn with Levi Branch and Big	Current Use: not in use, marginal storage
Pine Rd (approx. 3900 Big Pine Rd.)	Historic Use: burley tobacco
GPS Location: N35 50.095 / W82 46.693	Permission to visit property by: owner, Roos
Elevation: 1770'	(Rose) and Ben Geradts; 813-977-6992
Township: Walnut	
Vicinity: lower Big Pine Creek	The property is on the market for sale.
Approx date/decade built: 1930s	

ORIGINAL BARN characteristics

Integrity

x High __ Medium __ Low Condition _x_Good __Fair __Deteriorated __Ruin Add. Info.:

Function of original barn

____ general purpose

x livestock/hay

____ flue-cured tobacco

 $_x_$ burley tobacco

____bull face tobacco

___ dairy

___ other

Add. Info.: This barn is an example of a transitional form, as a livestock barn that was also built to air cure burley tobacco.

Type Construction of original barn

___ Post and Beam

___ timber frame

___ mortise and tenon

____ sawn lumber

___ hewn timbers

 $_x$ notched logs

____ stud frame

Add. Info.: notched log ends are flush, an uncommon method.

Original siding materials

- ___ milled boards
- ___ lattice
- _x_ exposed logs
- _____board and batten
- __ metal
- ____ shingles
- ___ other
- Add. Info.:

Orientation of siding

- ____ angled on diagonal
- ___ vertical
- ___ horizontal

Add. Info.: log throughout, including gables

Roof pitch or slope of original barn: 6.5 / 12

Roof type of original barn

- _x_ gable
- ___ broken gable
- ___ gambrel
- ____ shed
- __ monitor
- __ cupola
- ___ other
- Add. Info.:

Roofing materials of original barn

- _____ split wood shingles
- _____3-V metal
- ___ 3-u metal
- _x_ 5-V metal- current
- _____ stamped metal shingle
- ____ tar paper
- $_x$ unknown
- __ other

Add. Info.: There is no roof lath strips that would support split oak shingles and the existing 5-V metal roofing sits across the round pole purlins. It is likely however, that the original roof was split oak shingles, replaced at a later date.

Roof framing of original barn

- ____ round pole rafters
- ___ milled rafters
- ____ gambrel shallow trusses
- ____ gambrel with post and beam support

x round purlins

Add. Info.: purlins are spaced 30 inches apart and average 5"-6" in diameter.

Foundation of original barn

- _x_ Dry laid stone
- ____ wood sills on rock piers
- ___ mortared stone
- ___ concrete
- __ concrete block
- ____ columns/wood piers
- ____ posts on concrete footings

Add. Info.: a rock retaining wall supports a bank at the north end

Flooring of original barn

- _x_ dirt floor
- _x_ wood flooring: in loft
- ___ concrete slab

Add. Info.: round pole floor joists supporting loft floor are 27" +/- OC

Species of wood used in original barn

- ___ chestnut
- ____ other, list known species

Add. Info.: the logs appear to be exclusively white pine. Sawn boards are mostly oak, with some pine.

Hinges

- __ leather
- ___ wooden
- ___ wrought iron
- _x_ commercial metal
- ___ rubber
- ___ other
- Add. Info.:

Fasteners

- _x_ wire nails
- ___ cut nails
- ___ wrought spikes
- ___ wood pegs
- ___ other
- Add. Info.:

Tobacco tier poles vertical spacing

__ +/- 2 feet _x_ +/- 3 feet __ +/- 4 feet _____ other, list Add. Info.: vertical spacing ranges from 32" to 39". Horizontal spacing averages 44'.

Additional traditional features, list: The length of the roof is broken by another set of logs of deceasing lengths that mirror the end gable logs, to support the purlins.

This is a bank barn, but the bank was altered when the road was upgraded and no longer functions as a bank barn.

ALTERATIONS AND ADDITIONS characteristics

Has the original barn been altered or added to? No

Outbuildings: none surviving. There was a house approx. 80' to the west.

Setting and/or Surrounding Land Use: This barn is in a narrow stretch of the Big Pine Creek gorge with no bottom land nearby. It was part of an active farm when built, but most of the tillable land has returned to forest. Levi Branch road crosses the creek and continues east where it opens into a valley of more suitable farm land.

Historic Information: John Daniel Shelton, July 5 1882, d. May 11 1981, lived to be ninetynine years old. He spent much of his life in the Wilson Cove area of Big Pine where he built at least three other large log barns, on very steep land, which were likely flue-cured tobacco barns. According to family history, Shelton always built his barns and farmed "by the signs". This barn is an exceptional example of a round log bank barn using a massive rock retaining wall, saddle notches and the old tradition of continuing the log wall into the gable end. This requires that the two gable ends be part of a roof structure of round pole "purlins" that span the distance between log walls, and lock the gable end logs in place. The near-perfectly round logs form a barn 26 feet by 27 feet, and run 25 logs high, totaling 100 logs, plus 24 logs of decreasing lengths in the gable ends. The family recalls that his daughter-in-law, Pearl, helped fell and drag the logs by horse team, and hauled from many miles away on Doe Branch. The barn is in very good condition considering it is over eighty years old and sits in a damp creek bottom. The old house also stood nearby until the new road was built.

Primary source contacts: Jack Smith 645-6197- <u>elvert5@frontier.com</u> Other contacts: Steven Porter, grandson of Pearl, daughter-in-law of John Shelton (wife Belle), Luther Roberts

John Daniel Shelton, born on Little Pine, buried at Cedar Hill Cemetery, Alexander; children John Wm b. 1907, wife Pearl; Nellie Josephine b. 1909; Farlan b. 1910; Wayne Wilson b. 1913; Viola b. 1917 Shelton also lived up Wilson Cove Rd. in a log house;

Date Photos Taken: July 27, 2015

<u>Submitted By</u> Name: Taylor Barnhill Address: 226 Beech Glen Rd., Mars Hill, NC 28754 Phone home: Cell: 828-380-9336 Email: taylor.barnhill@yahoo.com