MADISON COUNTY BARN DOCUMENTATION PROJECT

Common Identity of Barn: Eason Allen Tweed barn Address of Barn: 4505 NC Hiway 212 GPS Location: N35-57.530 / W82- 42.177 Elevation: 1871' Township: Laurel Vicinity: lower Shelton Laurel Approx date/decade built: late 1800s Current Owner: Johnny Moore Historic Owner(s): Eason Tweed Current Use: workshop, storage Historic Use: livestock, general Permission to visit property by: Johnny Moore, owner

Outbuildings: corn crib, large burley tobacco barn

Setting and/or Surrounding Land Use: This barn is part of what was an originally large land holding by a prominent family in the Shelton Laurel valley. The property was in the ownership of the widower of a family descendant at the time of documentation, then transferred to the daughter.

Historic Information: Family members do not know the age of this barn but assume it was built by Eason Tweed. Eason Allen Tweed's life dates are: Feb. 26, 1858 - March 16, 1917. Eason Tweed's father was Abner Grainger (A.G.) Tweed: 1824 - Feb.4, 1907. A.G. Tweed was Sherriff of Madison County from 1870-1883. He also reportedly had 5,000 apple trees and made brandy for the U.S. Army. A.G. was a Civil War Veteran (1st Tenn. Cav., Union). A.G.s brother, Neely Tweed, was Madison County's first Clerk of Superior Court and is locally known for having killed Sherriff Ransom P. Merrill.

Photo below is of A.G., as an old man, with his wife Jane Pinner Tweed. Jane Pinner Tweed's father, Hugh Pinner, was the founder of Pinner's Cove in Buncombe County.

A.G. & Jane were first cousins. Jane's mother, Isabella Tweed Pinner, was a sister to A.G.'s father, James. (information provided by Steven Tweed)



Integrity

___ High __x_ Medium ___ Low Condition ___Good x___Fair

___Deteriorated ___Ruin Add. Info.:

Function of original barn

x general purpose

- _x_ livestock/hay
- ____ flue-cured tobacco
- ___ burley tobacco
- ___ bull face tobacco
- ___ dairy
- ___ other

Add. Info.: This barn is a rare example of a livestock barn that was never converted for burley tobacco. It does not have the typical lattice on the loft side walls.

Type Construction of original barn

___ Post and Beam

- _x_ timber frame partial
- _x_ mortise and tenon
- _x_ sawn lumber
- _x_ hewn timbers
- _x_ notched logs
- _x_ stud frame

Add. Info.: This barn is a half-height bank barn and an example of partial timber frame construction with mortise and tenon joinery with diagonal braces along exterior wall frame. The log pens are an unusual 13'- 6" square. It is a rectangular log barn, 35 feet 7 inches +/- X 42 feet 2 inches +/-. Log diameter ranges from 9 inches to 19 inches, the log walls being 7 to 9 logs high, and are a half dovetail notch. Wrought iron spikes and cut nails are present as are wire nails and commercial hinges. Rafters are 2x4s at 30" O.C. +/-. Short collar ties are present near the ridgeline, an uncommon feature. The mortise and tenon joinery is high quality and uses pegs and occasional wedges.

Original siding materials

x milled boards

- __ lattice
- _x_ exposed logs
- ___ board and batten

__ metal __ shingles __ other Add. Info.:

Orientation of siding

____angled on diagonal _x__vertical ____horizontal Add. Info.:

Roof pitch or slope of original barn: 12.5 / 12 on steepest slope, and 7 / 12 on lower slope

Roof type of original barn

- _x_ gable
- ___ broken gable
- ___ gambrel
- ____ shed
- ___ monitor
- __ cupola
- __ other
- Add. Info.: with two-slope slope

Roofing materials of original barn

- _x_ split wood shingles
- ____ 3-V metal
- ___ 3-U metal
- ___ 5-V metal
- ____ stamped metal shingle
- ___ tar paper
- ____ unknown
- ___ other

Add. Info.: Current roofing is corrugated metal.

Roof framing of original barn

- ____ round pole rafters
- _x_ milled rafters
- ____ gambrel shallow trusses
- ____ gambrel with post and beam support
- ____ round purlins
- Add. Info.: 2x4 rafters

Foundation of original barn _x_ Dry laid stone

- ____ wood sills on rock piers
- ___ mortared stone
- ___ concrete
- __ concrete block
- ____ columns/wood piers
- ____posts on concrete footings

Add. Info.: This barn is a bank barn but has an unusual "half" bank that is not supported by a rock retaining wall and extends to half way up the west side of the log pen, but separate from the log wall.

Flooring of original barn

x dirt floor _x_ wood flooring- in loft __ concrete slab Add. Info.:

Species of wood used in original barn

x chestnut _x_ other, list known species – oak, pine, etc. Add. Info.:

Hinges

- ___ leather
- ___ wooden
- ___ wrought iron
- _x_ commercial metal
- ___ rubber
- ___ other

Add. Info.:

Fasteners

- _x_ wire nails _x_ cut nails __ wrought spikes __ wood pegs __ other
- Add. Info.:

Tobacco tier poles vertical spacing: NA

___ +/- 2 feet ___ +/- 3 feet __ +/- 4 feet __ other, list

Add. Info.: unusual loft with no tier poles

Additional traditional features, list:

ALTERATIONS AND ADDITIONS characteristics

Has the original barn been altered or added to? Metal roofing, siding and posts on sheds sides has been replaced, roofing replaced, wood floor installed, steps added although may have replaced the original steps.



Date Photos Taken: May 5, 2014

<u>Submitted By</u> Name: Taylor Barnhill Address: 226 Beech Glen Rd., Mars Hill, NC 28754 Phone home: Cell: 828-380-9336 Email: taylor.barnhill@yahoo.com