MADISON COUNTY BARN DOCUMENTATION PROJECT

Common Identity of Barn: Thurman Briggs Address of Barn: 2501 Old Mars Hill Highway. Mars Hill, NC 28754 GPS Location: N35-48.028 / W82-31.919 Elevation: 2032' Township: Beech Glen Vicinity: Mars Hill/Forks of Ivy Approx date/decade built: 1954-56 Current Owner: Mark Peyton, 787-208-9458, markpeyton119@gmail.com Historic Owner(s): Thurman Briggs Current Use: storage Historic Use: livestock, burley tobacco Permission to visit property by: owner Mark Peyton

ORIGINAL BARN characteristics

Integrity

x High __ Medium __ Low Condition _x_Good __Fair __Deteriorated __Ruin Add. Info.:

Function of original barn

- _x_ general purpose
- _x_ livestock/hay
- _____flue-cured tobacco
- ____ burley tobacco
- ____bull face tobacco
- ___ dairy
- ___ other
- Add. Info.:

Type Construction of original barn

- _x_ Post and Beam
- ____ timber frame
- ___ mortise and tenon
- _x_ sawn lumber
- ___ hewn timbers
- ___ notched logs
- _x_ stud frame

Add. Info.: This is an example of a well built post WWII general purpose barn built exclusively for livestock and utility. The barn features typical elements of the late'40's early '50's barn construction.

Original siding materials

- _x_ milled boards
- _x_ lattice
- ____ exposed logs
- ____board and batten
- __ metal
- ____ shingles
- ___ other
- Add. Info.:

Orientation of siding

x angled on diagonal _x_ vertical _x_ horizontal Add. Info.:

Roof pitch or slope of original barn: 12/12 and 5/12

Roof type of original barn

___ gable

- ___ broken gable
- _x_ gambrel
- ___ shed
- __ monitor
- __ cupola
- ___ other

Add. Info.: this is not a true gambrel roof structure, but is supported by interiors posts

Roofing materials of original barn

- _____ split wood shingles
- _____3-V metal
- ____ 3-u metal
- _x_ 5-V metal
- _____ stamped metal shingle
- ___ tar paper
- ____ unknown
- ___ other
- Add. Info.:

Roof framing of original barn

- ____ round pole rafters
- _x_ milled rafters
- ___ gambrel shallow trusses
- _x_ gambrel with post and beam support
- ___ round purlins
- Add. Info.:

Foundation of original barn

- ___ Dry laid stone
- ____ wood sills on rock piers
- ___ mortared stone
- ___ concrete
- _x_ concrete block
- ____ columns/wood piers
- ____ posts on concrete footings
- Add. Info.: large sawn wood sills on scattered concrete blocks

Flooring of original barn

x dirt floor

x wood flooring

___ concrete slab

Add. Info.: wood flooring in tack room and loft

Species of wood used in original barn

___ chestnut

x other, list known species

Add. Info.: various common species

Hinges

- ___ leather
- ___ wooden
- ___ wrought iron
- _x_ commercial metal
- ___ rubber
- ___ other

Add. Info.:

Fasteners

- _x_ wire nails
- ___ cut nails
- ___ wrought spikes
- ___wood pegs
- ___ other
- Add. Info.:

Tobacco tier poles vertical spacing

_____+/- 2 feet _______ +/- 3 feet _________ theref ________ other, list Add. Info.: Additional traditional features, list:

ALTERATIONS AND ADDITIONS characteristics

Has the original barn been altered or added to? yes

Description of alterations and additions: Before the construction was completed, the owner was approached by neighbors to allow them to hang their burley tobacco in this barn, and he agreed to allow them to alter the barn with tier poles hanging for burley tobacco. Some other alterations have been made recently to open two stalls for a workshop space.

Condition of alterations

x good __ fair

__ poor

__ ruin

Add. Info.:

Function of barn alterations and additions

___ general purpose

__ livestock/hay

_____flue-cured tobacco

x burley tobacco

___ bull face tobacco

___ dairy

___ other

Add. Info.:

Type Construction alterations and additions

x Post and Beam

____ timber frame

___ mortise and tenon

____ sawn lumber

___ hewn timbers

___ notched logs

____ stud frame

Add. Info.:

Siding materials of alterations and additions

__ milled boards

__ lattice

___ exposed logs

____ board and batten

___ metal

____ shingles

__ other

Add. Info.:

Orientation of siding

____angled on diagonal ____vertical ____horizontal Add. Info.:

Roof pitch or slope of alterations and additions:

Roof type of barn alterations and additions

___ gable

- ___ broken gable
- ___ gambrel
- ___ shed
- ___ monitor
- __ cupola
- ___ other
- Add. Info.:

Roofing materials of alterations and additions

- ____ split wood shingles
- ____ 3-V metal
- ___ 3-u metal
- ___ 5-V metal
- _____ stamped metal shingle
- ___ tar paper
- ____ unknown
- __ other
- Add. Info.:

Roof framing of alterations and additions

- ____ round pole rafters
- ___ milled rafters
- ___ gambrel shallow trusses
- _____gambrel with post and beam support
- ____ round purlins

Add. Info.:

Foundation of alterations and additions

- __ Dry laid stone
- ____ wood sills on rock piers
- ___ mortared stone
- ___ concrete
- __ concrete block
- ____ columns/wood piers

___ posts on concrete footings Add. Info.:

Flooring of alterations and additions

__ dirt floor __ wood flooring __ concrete slab

Add. Info.:

Species of wood used in alterations and additions

___ chestnut

____ other, list known species

Add. Info.:

Hinges/ alterations and additions

- __ leather
- __ wooden
- ____ wrought iron
- ___ commercial metal
- ___ rubber
- __ other
- Add. Info.:

Fasteners/ alterations and additions

- ____ wire nails
- ___ cut nails
- ___ wrought spikes
- ___wood pegs
- __ other
- Add. Info.:

Tobacco tier poles vertical spacing/ alterations and additions

____ +/- 2 feet ____ +/- 3 feet ____ +/- 4 feet ____ other, list Add. Info.:

Outbuildings: one storage shed, now on adjacent property

Setting and/or Surrounding Land Use: This site is a classic early twentieth century family commercial and living setting where the family lived in the gas station/store and ran the business while operating basic farm activities with chickens, draft horses, garden and some crops. This family business began as an earlier gas station and store, down the hill from the barn, on the original Burnsville Highway built in 1922 as part of the US/NC highway expansion to accommodate the new automobile age. It is a good example of the progression over time of

the changes in highway location and its dominance of the landscape, replacing farmland and home sites. The early road (1922) ran primarily following the old horse and wagon road that closely followed the creek (Little Ivy Creek) with many crossings at fords. The second generation road, built circa 1950 was located uphill skirting the hillsides and cutting through other land uses. The last generation of road is the current I-26 built higher up the valley and cutting through entire hillsides.

Historical Background: Thurman Briggs was born Nov 31, 1914, deceased Jan 21st, 1992, and is buried at the Mars Hill town cemetery. Surviving family members recall very little about this barn although they believe it was built circa 1954-56 following the construction of Briggs' new store and gas station, adjacent to the barn. The gas station was built for Briggs by Esso Oil Co. and is a good example of the mid-20th century rural highway gas station and country store. The barn was built by Briggs' cousin Stanley Marshbanks and his brother-in-law Kyle Jamerson. They also worked on the store construction.

The Briggs family is also representative of a typical extended family living within a common valley, including in this example the Willis,' Marshbanks, Andersons, and Briggs, all of which had close associations with Mars Hill College. Thurman Briggs frequently employed one of the nearby African American families, the Briscoes, as tenant farmers and workers. The Briscoes are the primary family associated with the historic Rosenwald School located on the ridge above the Willis and Briggs property.

Thurman Briggs' daughter, Barbara Willard, remembers many stories from her childhood living at the store and barn, including seeing a "panther", or cougar, perched up in the tier poles of the barn after raiding the chicken coop. She also recounts visits by gypsy caravans, the women dressed in traditional gypsy dresses of long billowing skirts with loose blouses into which they would hide shoplifted food from the store.

Date Photos Taken: <u>Submitted By</u> Name: Taylor Barnhill Address: 226 Beech Glen Rd., Mars Hill, NC 28754 Phone home: Cell: 828-380-9336 Email: taylor.barnhill@yahoo.com