MADISON COUNTY BARN DOCUMENTATION PROJECT

Common Identity of Barn:	Vicinity: Upper Big Pine Creek valley
George Washington Wild (b 1861) and	Approx date/decade built: early 20 th century
Laura Ratcliff Wild Livestock/ Dairy barn	Current Owner: Jeff and Cindy Moore
Address of Barn:	Historic Owner(s): George W. Wild, Claude Wild,
31 South Fork Road, Marshall NC	Donald and Geraldine Wild
GPS Location: N35 47.130 / W82 48.677	Current Use: storage
	Historic Use: livestock and dairy, burley tobacco
Elevation: 2509'	Permission to visit property by: Jeff Moore
Township: Walnut	Phone: 828-649-1143

ORIGINAL BARN characteristics

Integrity

x High __ Medium __ Low Condition __Good _x_Fair __Deteriorated __Ruin Add. Info.:

Function of original barn

____ general purpose

_x_livestock/hay

____flue-cured tobacco

___ burley tobacco

____bull face tobacco

x dairy

___ other

Add. Info.:

Type Construction of original barn

x Post and Beam

___ timber frame

___ mortise and tenon

x sawn lumber

___ hewn timbers

___ notched logs

 $_x$ stud frame

Add. Info.: This large barn measures 52 feet by 58 feet and has an unusual 3-sloped gambrel roof, taking advantage of the newly introduced metal roofing. Hidden within the

rectangular barn is an octagon-shaped structure that forms eight animal stalls, coming together in the center to allow hay to be pitched into all eight stalls from a central hay chute in the hay loft above.

Original siding materials

x milled boards

x lattice

- ___ exposed logs
- ___ board and batten
- __ metal
- ____ shingles
- ___ other

Add. Info.: original siding conforms to the conventional use of lattice and lapped poplar board siding used on the large A-gable barns of the late 19th century and early twentieth century.

Orientation of siding

____ angled on diagonal

____ vertical

x horizontal

Add. Info.: for a large hayloft, the extent of cover of the siding is unusual, as it does not allow as much air flow.

Roof pitch or slope of original barn: 10/12; 6.5/12; 3.5/12

Roof type of original barn

___ gable

- ___ broken gable
- _x_ gambrel
- ___ shed
- __ monitor
- __ cupola
- __ other

Add. Info.: this is a 3-slope gambrel and the only one found in Madison County to date

Roofing materials of original barn

_____ split wood shingles

- ____ 3-V metal
- ___ 3-u metal
- _x_ 5-V metal
- _____ stamped metal shingle
- ___ tar paper
- ____ unknown

___ other

Add. Info.: The 5-V metal roofing may not be the original. Older metal roofing was usually 3-V.

Roof framing of original barn

____ round pole rafters

x milled rafters

___ gambrel shallow trusses

x gambrel with post and beam support

____ round purlins

Add. Info.: rafters are at an uncommon 36" spacing

Foundation of original barn

x Dry laid stone

____ wood sills on rock piers

___ mortared stone

___ concrete

___ concrete block

____ columns/wood piers

____ posts on concrete footings

Add. Info.: this is a bank barn and has a massive rock retaining wall supporting the bank

Flooring of original barn

x dirt floor

x wood flooring – in loft, interior corn crib, and tack room

___ concrete slab

Add. Info.:

Species of wood used in original barn

x chestnut

x other, list known species

Add. Info.: various other species

Hinges

__ leather __ wooden

x wrought iron

x commercial metal

___ rubber

___ other

Add. Info.:

Fasteners

- _x_ wire nails
- ___ cut nails
- ___ wrought spikes
- ___wood pegs
- ___ other

Add. Info.:

Tobacco tier poles vertical spacing

____+/- 2 feet ____+/- 3 feet ____+/- 4 feet _____other, list Add. Info.:

Additional traditional features, list: stall doors have varying latch types. The interior may have the remains of a grain thrashing floor. This is the only barn in Madison County found to date with a wood round silo. Note: the silo was severely damaged by wind in the spring of 2015.

ALTERATIONS AND ADDITIONS characteristics

Has the original barn been altered or added to? Yes

Description of alterations and additions: several shed additions have been added over the years, including a wood shed, a garage, a milking room, and two storage rooms. The loft has been adapted to hang burley tobacco.

Condition of alterations

__ good _x_ fair _x_ poor __ ruin Add. Info.:

Function of barn alterations and additions

x general purpose __ livestock/hay __ flue-cured tobacco _x_ burley tobacco __ bull face tobacco _x_ dairy __ other Add. Info.: milking room

Type Construction alterations and additions

x Post and Beam

___ timber frame

___ mortise and tenon

x sawn lumber

___ hewn timbers

__ notched logs

x stud frame

Add. Info.:

Siding materials of alterations and additions

x milled boards

__ lattice

- ____exposed logs
- ____board and batten
- x__ metal
- ____ shingles
- ___ other
- Add. Info.:

Orientation of siding

____angled on diagonal _x__ vertical x___ horizontal Add. Info.:

Roof pitch or slope of alterations and additions: 2 / 12

Roof type of barn alterations and additions

- ___ gable
- ___ broken gable
- ___ gambrel
- _x_ shed
- __ monitor
- __ cupola
- ___ other
- Add. Info.:

Roofing materials of alterations and additions

- ____ split wood shingles
- _____3-V metal
- ___ 3-u metal
- _x_ 5-V metal
- _____ stamped metal shingle
- ___ tar paper
- ____ unknown
- ___ other
- Add. Info.:

Roof framing of alterations and additions

- ____ round pole rafters
- _x_ milled rafters
- ___ gambrel shallow trusses
- _____gambrel with post and beam support
- ____ round purlins

Add. Info.:

Foundation of alterations and additions

- ___ Dry laid stone
- ____ wood sills on rock piers
- ___ mortared stone
- ___ concrete
- __ concrete block
- _x_ columns/wood piers
- _x_ posts on concrete footings
- Add. Info.:

Flooring of alterations and additions

x dirt floor

- ___ wood flooring
- x___ concrete slab

Add. Info.:

Species of wood used in alterations and additions

x chestnut _x_ other, list known species Add. Info.:

Hinges/ alterations and additions

- __ leather
- ___ wooden
- ___ wrought iron
- _x_ commercial metal
- ___ rubber
- ___ other
- Add. Info.:

Fasteners/ alterations and additions

- _x_ wire nails
- ___ cut nails
- ___ wrought spikes
- ___wood pegs
- ___ other
- Add. Info.:

Tobacco tier poles vertical spacing/ alterations and additions

_____+/- 2 feet __x___+/- 3 feet ______+/- 4 feet _______ other, list Add. Info.: average is 39" vertical spacing Outbuildings: the remains of a spring house is behind the barn.

Setting and/or Surrounding Land Use: this farm is located at a large opening in the upper Big Pine Creek valley and is prime farm land, and at the junction of three roads that diverge into other valleys or up the mountain. It was the community center with a church, store, electric generator plant, and grist mill.

Historic Information:

The George and Laura Wild barn and silo represent uncommon innovations of the late 19th and early 20th centuries. Born on Big Pine Creek in 1861, George Washington Wild bought 180 acres from A. M. Gudger of Buncombe County on April 5, 1884. He later demonstrated the expert farming and business acumen of his father Jacob, operating a dairy and tobacco farm, a saw mill, grist mill, post office, blacksmith shop, and store. In 1919 Wild was elected to serve in the NC General Assembly, during which time he introduced a law to require fencing of livestock in order to end the tradition of livestock ranging free. He also had the first electricity in the valley, generated first by a kerosene engine, then by an overshot water wheel. The wooden silo, damaged by wind in early 2015, was the first silo on Big Pine Creek, and is the only wooden silo to survive in Madison County. This large barn measures 52 feet by 58 feet and has an unusual 3sloped gambrel roof, taking advantage of the newly introduced metal roofing. Hidden within the rectangular barn is an octagon-shaped structure that forms eight animal stalls, coming together in the center to allow hay to be pitched into all eight stalls from a central hay chute in the hay loft above. G. W. Wild's grandson Don later related the story of the origin of this unique barn design: a traveling salesman, or "drummer", from Tennessee sold Wild a set of blueprints for the barn design, an unheard-of innovation for these remote mountains. The large loft was later adapted to air-cure burley tobacco.

Date Photos Taken: August 3, 2012 by Diane Van Helden; Sept 10, 2013; May 5, 2015 by Taylor Barnhill

<u>Submitted By</u> Name: Taylor Barnhill Address: 226 Beech Glen Rd., Mars Hill, NC 28754 Phone home: Cell: 828-380-9336 Email: taylor.barnhill@yahoo.com