MADISON COUNTY BARN DOCUMENTATION PROJECT

Current Owner: Genevieve and Larry Burda

Common Identity of Barn: Floyd Wallin barn

(1905 to 1992)	Historic Owner(s): Wallin family, Floyd Wallin,
Address of Barn: 3152 NC Hiway 212	Jerry Wallin
GPS Location: N35 57.148 / W82 43.202	Current Use: storage
Elevation: 1789'	Historic Use: livestock, burley tobacco
Township: Laurel	Permission to visit property by: owner, Larry
Vicinity: Shelton Laurel Creek Approx date/decade built: 1890 to 1910	Burda:
Approx date/decade built. 1890 to 1910	
Outbuildings: none survived	
valley and is not situated within areas of larger be	barn is placed in the lower end of the Shelton Laurel ottom land, but in a narrow section in the bend of 50 feet from the creek but high enough to be free of
Eason Tweed barn and very likely built by the sa	ut this barn's history. The barn is very similar to the ame builder(s). The primary difference between the o log pens of the Tweed barn. The loft level has no apport flooring.
Note: 9.9.16 Joe Tweed, who may have built the There is another barn of this design farther up the	
ORIGINAL BARN characteristics	
T /	
Integrity	
High _x_ Medium	
Low	
Condition	
Good	
Fair	
_x_Deteriorated	
Ruin	
Add. Info.:	
Function of original barn	
x general purpose	
x livestock/hay	
flue-cured tobacco	
burley tobacco	
bull face tobacco	
dairy	
other	

Add. Info.:
Type Construction of original barn Post and Beam timber framex_ mortise and tenonx_ sawn lumberx_ hewn timbers notched logs stud frame Add. Info.: It does not have the typical lattice on the loft side walls. The original barn is a good example of local mortise and tenon joinery, timber frame, with some diagonal braces within the frame. The 4 log pens are 12' square separated by 12' +/- cross hallways. It is a roughly square log barn, 36'-8" +/- X 36' +/ Log diameter averages 10" to 12 inches, the log walls being 5 high on upper end and 6 logs high on lower end, and are a half dovetail notch. Wrought iron spikes and cut nails are present as are wire nails and commercial hinges. Rafters are 2x4s at 24" O.C. +/ The mortise and tenon joinery is high quality and uses pegs and occasional wedges. The posts and beams in the old part of the barn are an unusually large 8"X 8". The initials "E G" are carved into a log with a chisel and is likely original and could have been carved by a Gentry man, to be confirmed.
Original siding materials _x_ milled boards lattice _x_ exposed logs board and batten metal shingles other Add. Info.:
Orientation of siding angled on diagonal verticalx_ horizontal Add. Info.:
Roof pitch or slope of original barn: 13 / 12; 7 / 12
Roof type of original barn _x_ gable broken gable gambrel shed monitor cupola

other Add. Info.: this is an unusual gable roof profile, sloped in two pitches, and is a type that appears multiple times in the Shelton Laurel valley, and it may be a type that was built by a Tweed, since the Eason Tweed barn has the same profile.
Roofing materials of original barn _x_ split wood shingles _ 3-V metal _ 3-u metal _ 5-V metal _ stamped metal shingle _ tar paper _ unknown _ other Add. Info.: replacement roofing is corrugated metal. Lath strips are spaced for split oak shingles
Roof framing of original barn round pole raftersx milled rafters gambrel shallow trusses gambrel with post and beam support round purlins Add. Info.:
Foundation of original barn _x_ Dry laid stone _x_ wood sills on rock piers _ mortared stone _ concrete _ concrete block _ columns/wood piers _ posts on concrete footings Add. Info.:
Flooring of original barn _x_ dirt floor _x wood flooring – in original loft _ concrete slab Add. Info.:
Species of wood used in original barn _x_ chestnut _x_ other, list known species Add. Info.: pine, oak, hemlock, poplar

Hinges leather wooden wrought iron _x_ commercial metal rubber other Add_Info:
Add. Info.: Fasteners _x_ wire nails x cut nails x wrought spikes _x_ wood pegs _ other Add. Info.:
Tobacco tier poles vertical spacing +/- 2 feet +/- 3 feet +/- 4 feet other, list Add. Info.: NA
Additional traditional features, list: This barn is very similar to the Eason Tweed barn and very likely built by the same builder(s). The main difference is the four log pens instead of the two log pens of the Tweed barn. The loft level has no flooring and no apparent structure in place to support flooring.
ALTERATIONS AND ADDITIONS characteristics
Has the original barn been altered or added to? Yes
Description of alterations and additions: addition for burley tobacco, thought to be built in the 1940's. Also tier poles added to original barn for burley or Bull Face tobacco.
Condition of alterations good fairx_ poor ruin Add. Info.:
Function of barn alterations and additions general purpose

livestock/hay	
flue-cured tobacco	
x burley tobacco	
bull face tobacco	
dairy	
other	
Add. Info.:	
Type Construction alterations and additions	
x Post and Beam	
timber frame	
mortise and tenon	
x sawn lumber	
hewn timbers	
notched logs	
stud frame	
Add. Info.: this is typical post and beam burley tobacco type barn	•
Siding materials of alterations and additions	
x milled boards	
lattice	
exposed logs	
board and batten	
metal	
shingles	
other	
Add. Info.:	
ruu. Iliio	
Orientation of siding	
angled on diagonal	
x vertical	
horizontal	
Add. Info.:	
Roof pitch or slope of alterations and additions: 4.5 / 12	
Roof type of barn alterations and additions	
x gable	
broken gable	
gambrel	
shed	
monitor	
cupola	
other	
Add. Info.:	
11001	

Roofing materials of alterations and additions
split wood shingles
3-V metal
3-u metal
x 5-V metal
stamped metal shingle
tar paper
unknown
other
Add. Info.: replacement roofing on original barn is corrugated meta
rad. Info replacement footing on original barn is corragated meta
Roof framing of alterations and additions
round pole rafters
x milled rafters
gambrel shallow trusses
gambrel with post and beam support
gambler with post and beam support round purlins
Add. Info.:
Add. IIIIO
Foundation of alterations and additions
x Dry laid stone
· · · · · · · · · · · · · · · · · · ·
x wood sills on rock piers mortared stone
concrete
concrete block
columns/wood piers
posts on concrete footings
Add. Info.:
Flooring of alterations and additions
x dirt floor
wood flooring
concrete slab
Add. Info.:
Species of wood used in alterations and additions
chestnut
x other, list known species
Add. Info.: pine, oak, hemlock, poplar
Hinges/ alterations and additions
leather
wooden
wrought iron
commercial metal
rubber

other
Add. Info.: NA
Fasteners/ alterations and additions
x wire nails
cut nails
wrought spikes
wood pegs
other
Add. Info.:
Tobacco tier poles vertical spacing/ alterations and additions
+/- 2 feet
+/- 3 feet
x +/- 4 feet
other, list
Add. Info.: Tier poles in older section may indicate early use of Bull Face tobacco curing
with tier poles at 36" to 39" apart, but this is not confirmed.
' '

Date Photos Taken: March 4, 2014

Submitted By

Name: Taylor Barnhill Address: 226 Beech Glen Rd., Mars Hill, NC 28754 Phone home: Cell: 828-380-9336

Email: taylor.barnhill@yahoo.com